





WS449

STRIKE

	WS445 BODY	1	3-12 THREADED STUD
INSTRUCTIONS: 1. OPEN DOOR TO DESIRED POSITION. 2. PLACE STRIKE AND HOLDER IN DESIRED LOCATION. 3. LOCATE MOUNTING HOLES FOR BOTH THE STRIKE AND THE BODY. 4. PREPARE MOUNTING HOLES AS NECESSARY.		1	LEAD EXP SHIELD
		1	#8 X 1" OPHWS
	WS449 BODY	3	#12 X 14" OPHWS
		3	#12 PLASTIC SHIELD

5. INSTALL BODY AND STRIKE.

WS445 & WS449 IVES MANUAL WALL HOLDER

INSTALLATION TEMPLATE

R) Security & Safety®

QTY

NOTE: DIMENSIONS IN () ARE MILLIMETERS.

TEMPLATE INST.WS445-449_0

DATE: 09-01-01

SCREW DETAILS

#8 X 1" OPHSMS